


**PORT NOTICE TO MARINERS**

**NO. 4 OF 2021**

NOTICE IS HEREBY GIVEN that Falmouth Harbour Commissioners have installed two Advanced Mooring Systems off Flushing Beach in the following approximate locations.

50 deg 9.7' N 005 deg 3.7' W and 50deg 9.7' N 005' 3.6'W



These buoys are not suitable for mooring and due to floats used along the length of chain to raise the chain off the seabed (see fig 1) chain may be closer to the surface than normally expected. Mariners should navigate with care in the area.




Fig 1 Sterling Mooring Arrangement<sup>1</sup>

These buoys demarcate an area for seagrass regeneration where 11 swinging moorings have been removed to reduce the impact of these moorings on the seagrass. Mariners should not anchor or lay gear on the seabed in this area to minimise additional damage to the seagrass.

More information is available from our website by clicking on the following link: [Sea Grass Regeneration in Falmouth](#)

HARBOUR OFFICE  
FALMOUTH  
TR11 3JQ

DUNCAN PAUL  
HARBOUR MASTER  
24<sup>th</sup> MAY 2021