




Falmouth Harbour
Commissioners

PORT NOTICE TO MARINERS

NO. 20 OF 2019

FABTEST SITE CARDINAL BUOY RECOVERY

NOTICE IS HEREBY GIVEN that the South Cardinal buoy has been removed from position $50^{\circ} 06'.165$ N $004^{\circ} 59'.632$ W that was within the FaBTest site.



(© UKHO Not for navigation)

The other three remaining cardinal buoys remain onsite and will also be removed when a suitable weather window occurs.

North Cardinal	$50^{\circ} 06'.327$ N	$004^{\circ} 59'.641$ W	Flash Q 1s
East Cardinal	$50^{\circ} 06'.274$ N	$004^{\circ} 59'.555$ W	Flash VQ (3) 5s
West Cardinal	$50^{\circ} 06'.272$ N	$004^{\circ} 59'.723$ W	Flash Q (9) 15s

**HARBOUR OFFICE
FALMOUTH
TR11 3JQ**

**M J SANSOM
HARBOUR MASTER
9th August 2019**