



Falmouth Harbour
Commissioners

PORT NOTICE TO MARINERS


NO. 27 OF 2018

PROTOTYPE ENERGY DEVICE – CARDINAL MARKS

NOTICE IS HEREBY GIVEN that the south cardinal mark that is in the position $50^{\circ} 06'.165\text{ N}$ $004^{\circ} 59'.632\text{ W}$, Flash VQ (6) + LF1 10s will be temporarily removed for essential work on Thursday 4th October by the vessel Boy Brendan.

All surface markers located within the Cardinal Buoy pattern will also be removed, the other three cardinal marks will remain on the site in the positions below:

North Cardinal	$50^{\circ} 06'.327\text{ N}$	$004^{\circ} 59'.641\text{ W}$	Flash Q 1s
East Cardinal	$50^{\circ} 06'.274\text{ N}$	$004^{\circ} 59'.555\text{ W}$	Flash VQ (3) 5s
West Cardinal	$50^{\circ} 06'.272\text{ N}$	$004^{\circ} 59'.723\text{ W}$	Flash Q (9) 15s



(© UKHO Not for navigation)

Whilst surface navigation is not impeded within the pattern of buoys, Mariners are advised to navigate with caution in this area and to refrain from engaging in fishing and anchoring activities within 250m of any of the remaining buoys.

This notice is self-cancelling when the south cardinal mark is reinstated on completion of the proposed works.

**HARBOUR OFFICE
FALMOUTH
TR11 3JQ**

**M J SANSOM
HARBOUR MASTER
3rd October 2018**