



Falmouth Harbour  
Commissioners

**PORT NOTICE TO MARINERS**

**NO. 02 of 2017**

**8 Knot Speed Limit Light.**

**NOTICE IS HEREBY GIVEN** the light on 8 knot speed limit buoy, character Fl (5) 20s, position 50° 09.54'N 005° 03.21'W, has been reported as missing.

Mariners are requested to navigate with caution in this area.

This notice will be self cancelling upon repair of the light.

**HARBOUR OFFICE  
FALMOUTH  
TR11 3JQ**

**M J SANSOM  
HARBOUR MASTER  
26 April 2017**