



Falmouth Harbour  
Commissioners


## PORT NOTICE TO MARINERS

NO. 04 of 2019

### FabTest Site E Cardinal Buoy Unlit.

**NOTICE IS HEREBY GIVEN** that the East Cardinal light positioned within the Falmouth Bay FabTest area,  $50^{\circ} 06'.274$  N,  $004^{\circ} 59'.555$  W Fl VQ (3) 5s has been reported being unlit. The Buoy is part of a pattern marking the position of a submerged wave energy generator (when deployed) and the North, South and West Cardinal lights are operating normally.

Mariners are advised to navigate with caution in this area at night.



(© UKHO Not for navigation)

This notice is self-cancelling when the light has been reinstated

**HARBOUR OFFICE  
FALMOUTH  
TR11 3JQ**

**M J SANSOM  
HARBOUR MASTER  
22<sup>nd</sup> January 2019**