



Falmouth Harbour
Commissioners

PORT NOTICE TO MARINERS

NO. 11 OF 2020

New Speed Limit Buoys

NOTICE IS HEREBY GIVEN that two new 6 knot speed limit buoys have positioned in the entrance to Falmouth inner harbour.

Buoy 1 has a flash character Fl(5)Y.20s and is in position $50^{\circ} 9.545'N$ $005^{\circ} 3.104'W$, Buoy 2 is unlit and in position $50^{\circ} 9.620'N$ $005^{\circ} 3.162'W$.

The old 8 knot speed limit buoys have been removed.



HARBOUR OFFICE
FALMOUTH
TR11 3JQ

M J SANSOM
HARBOUR MASTER
20th April 2020